

Vertical automatic stand STAV

User Manual

Plik: 2015-11-19 statyw STAV GB

Spis treści:

| 1. | Intro | oduction | 3 | | | |
|-----|-------------------|-----------------------|----|--|--|--|
| 2. | Cor | nplete set | 3 | | | |
| 3. | Tec | hnical data | 3 | | | |
| 4. | Sta | nd keys | 4 | | | |
| 5. | Saf | ety rules | 5 | | | |
| 6. | Dis | posal rules | 5 | | | |
| 7. | Pre | paring to work | 6 | | | |
| 8. | Ger | neral operation rules | 7 | | | |
| 9. | • | | | | | |
| 10. | | | | | | |
| 11. | Mai | in menu | 10 | | | |
| 12. | Ref | erence position | 10 | | | |
| 13. | Mai | nual mode | 10 | | | |
| 14. | Aut | omatic mode | 11 | | | |
| 15. | Settings | | 12 | | | |
| | 15.1 | Motion prog. editing | | | | |
| | 15.2 | Communication | 14 | | | |
| | 15.3 | Maximal force (Fmax) | | | | |
| | 15.4 | New PIN | | | | |
| | 15.5 Service menu | | | | | |
| Com | munica | ntes | 16 | | | |

1. Introduction

STAV500 vertical test stand with electric drive is designed for FB50, FB200, FB500, FC50, FC200 and FC500 force gauges. Thanks to precise programming motion mechanism STAV500 enables to perform precise measurements during e.g. material resistance testing.

2. Complete set

Basic set consists:

- 1. Automatic stand
- 2. Mounting element (force meter mounting)
- 3. Power supply

3. Technical data

| Туре | Automatic stand STAV |
|---------------------------------|----------------------------|
| Maximal tested force (max) | 500N |
| Stroke (travel) | 300mm |
| Maximal speed | 300mm/min |
| Motion programmes memory | 10 |
| Max steps quantity in one cycle | 8 |
| Working temperaturę | 0÷+40°C |
| Interfaces | RS232C, USB |
| Power supply | -230V 50Hz 100VA / 24V 4 A |
| Weight | 22,5kg |

4. Stand keys



- turn on / off the stand,
- STOP safety button that disconnects motor's supply,
- back / during inscribing data used for deleting or used for returning to previous position (inscribing PIN code),
- enter (choosing option) / during inscribing data adds another position or used for moving to next position (inscribing PIN code),
- return to main screen.

Knob enables to move cursor up or down (moving the knob right or left) and choosing selected option (by pressing the knob).

5. Safety rules



It is necessary to follow the safety rules. Obeying this rules is crucial to avoid electrical shock, damaging the stand or other connected devices.

- Repairs and necessary regulations can be done by authorized personnel only
- To avoid fire risk use a feeder of an appropriate type (supplied with stand) and supply voltage must be compatible with specified technical data.
- Do not use the stand if the cover is open.
- Do not use the stand in explosive conditions.
- Do not use the stand in high humidity environment.
- If the stand does not seem to operate properly, turn it off and don't use it until checked by authorized service centre.
- During measurements keep safe distance from the moving elements and the sample.

6. Disposal rules



According to current acts of low about protection of natural environment, wasted balances should not be put into waste containers together with ordinary waste.

 Wasted stand after operation period can be delivered to units authorised for gathering wasted electronic devices or to the place where it was bought.

7. Preparing to work

The stand must be used in room where the following requirements must be fulfilled: temperature must be between 0 to 40° C, air humidity $20\% \div 80\%$.



Stand must be set in room in such way as to allow easy access to safety button STOP!

Preparing device to work:

- 1. Put the stand on flat stable surface.
- 2. Carefully mount a force meter to the stand by using supplied mounting element.
- 3. Connect supply to stand.
- 4. Connect force meter to supply (if user doesn't use internal accumulators).
- 5. Turn on the force meter (press ON/OFF) and the stand (press I/Q).
- 6. The stand is ready to work.

8. General operation rules



During work keep hands in safe distance from sample and moving parts!



In case of any danger of losing health immediately press safety button STOP located on the device's front!

- 1. Make every effort to put the sample safetly and stable before starting measurements.
- 2. During work keep hands in safe distance from sample and moving parts.


9. Communication interface

The stand is equipped with two serial interfaces: RS232C and USB.

RS232C is used to connect the stand to force meter in order to receive actual force value from the force meter.

USB is used to connect computer with stand in order to send measurements to computer.

10. Dimensions



11. Main menu

After turning on the stand following menu appears:

Main menu

Manual mode

Settings Reference position

Automatic mode

User by turning knob changes selected position on the screen and enters it by pressing the knob or \rightarrow key. Exit from selected option by pressing \leftarrow .

12. Reference position

After turning on the stand and before measurements start user must select *Reference position* – this option moves the force meter to base position.

Thanks to base position driver can evaluate start position.

Setting base position must be executed after each ON/OFF.

Setting base position is required to use automatic mode.

13. Manual mode

In manual mode user by turning the knob moves force meter mounted on stand.

Manual mode

K = +0 imp/sek
V = +0 mm/min
X = +0.00 mm
F = +0.00 N

On the screen actual information are displayed:

 $K-knob\ rotary\ speed\ (impulse/second),$

V – force meter travel speed (mm/min),

X – force meter position (mm),

F - force value (N; displayed if the force meter is connected to stand by RS232C) Pressing knob will cause displaying sign *UP Down* and automatic moving the force meter with maximal speed in chosen direction.

Attention:

If before choosing manual mode user didn't set base position the X parameter will show "?" symbol.

14. Automatic mode

Docition

After choosing in main menu *Automatic mode*, the user chooses motion programme (programmed earlier by user: *Settings* menu \rightarrow *Motion programs editting*). After choosing proper programme by using knob user enters chosen setting and following positions indicate:

| Position name | Description | |
|------------------------|---|--|
| Start | Measurement start. | |
| Go to ref. pos. | Stand goes to base position for this programme. | |
| Reset cycle Counter | Zeroing motion cycle counter. | |
| V[mm/min] | Actual speed. | |
| x[mm] | Actual position. | |
| F[N] | Actual force on force meter display. | |
| Cycle no. | Actual cycle number. | |
| Step | Actual step number (each cycle can be divided into max 8 steps) | |
| x t F tc | Condition of actual step dependent on movenet, time force or cycle time | |
| t step [sek] | Actual step time. | |
| t cycle [sek] | Actual cycle time. | |
| t motion [sek] | The whole motion actual time | |

After setting reference position for chosen programme (*Go to ref. pos.*) we choose *Start* and start measurement. User checks actually displayed data eg. actual motion speed or actual cycle number.

15. Settings

Entrance to settings is locked with PIN code.

Insert PIN: 0****

Default PIN code is "000000" but it can be changed. By using \leftarrow and \rightarrow keys change indicatior position, move the knob to choose digit, press the knob to confirm inscribed PIN code. After entering settings submenu user can edit motion programmes, communication settings, menu language, maximal force, change PIN code and enter service menu (only for AXIS staff).

Settings menu

Motion prog. editing Communication

Language : english Fmax[N] : 100

New PIN

Service menu

15.1 Motion prog. editing

Motion prog. editing enables inscribing motion program settings such as eg. reference position, cycles quantity or steps quantity in one cycle. By using this settings user has many options to adjust programmed motion to his needs and sample. Precise description of each option below:

| Name | Values | Description |
|----------------------|--------------|--|
| Name | Max 14 signs | Motion program name edition |
| Reference pos. | - | Displays actual reference position. |
| Set reference pos. | - | Setting reference position. |
| Positive dir. | Down Up | Setting direction down or up as positive. |
| Cycle count | 1 ÷ 9999 | Setting measurement cycles quantity. |
| Steps count | Max 8 | Setting steps quantity in one cycle. |
| Manual mode | - | Preview in manual mode. |
| Motion prog. test | - | Motion program test. STAV/STAH will execute 1 cycle according to settings. |
| Step n – test | - | N-step test. STAV/STAH will execute n-step according to settings. |
| Speed | 20-300 | Setting movement speed [mm/min] for n-step. |
| | | Step will be executed until chosen condition will be completed: |
| | χ< | Movement value (position) smaller than |
| Continue | χ> | Movement value (position) bigger than |
| condition step | F< | Force value smaller than |
| | F> | Force value bigger than |

| | t< | Step time under |
|---------------|---------|---|
| | tc< | Step time over |
| | d< | Covered distance smaller than |
| One of below: | | |
| [mm] | 0-200mm | Inscribing position value or covered distance depending on chosen continue condition step |
| [N] | 0-200N | Inscribing force value if F< or F> condition was chosen |
| [sek] | 0-200s | Inscribing time value if t< or tc< value was chosen |

Depending on steps quantity menu positions quantity increases.

After setting all settings user exits by using \leftarrow key.

To start programmed motion user goes back (using \leftarrow key) to main menu and chooses *Automatic mode* position. Then user chooses proper motion program name (chapter 14).

15.2 Communication

In *Communication* submenu user can set RS232C serial interface parameters. User can choose information send to computer: cycle number, time, position and force. Using knob user selects which information will be send.


| Communication | | |
|---------------|----------|--|
| Period | : 000100 | |
| Baud | : 128000 | |
| Cycle no. | : 🗆 | |
| Time | :□ | |
| Position | :□ | |
| Force | : 🗆 | |

15.3 Maximal force (Fmax)

Setting maximal force, which can act on force meter. Fmax secures force meter from overloading. To use it connect force meter by RS232 joint to the stand and check if on stand's display there's information about actual force. Maximal value possible to set is 500N.

15.4 New PIN

New PIN submenu enables to change PIN code that secures access to Settings menu. Using \leftarrow and \rightarrow keys user changes indicator position, by moving knob digit value changes and then by pressing knob user confirms new PIN. New PIN must be inscribed twice to not make any mistake.



15.5 Service menu

Service menu is only for AXIS service.

Communicates

| Communicate/ state | Reason | Solution | |
|-----------------------|---|---|--|
| POSITION UNKNOWN | Reference position is not known | Choose in main menu Reference position | |
| NO SUPPLY | Stand engine supply off – security STOP buton pressed | Turn off STOP button. If the button is off then contact AXIS service. | |
| OVERLOAD | Stand loaded above Fmax value | Change Fmax value or use other sample which needs lower force. If still the stand is overloaded contact AXIS service. | |



Declaration of Conformity

The last two digits of the year in which the CE marking was affixed: 16

We:

AXIS Spółka z o.o. 80-125 Gdańsk, ul.Kartuska 375B

confirm with all responsibility that the stand:

STAV500

marked with $C \in C$ comply with the following:

Directive 2004/108/EWG EWG (electromagnetic compatibility) and harmonized norms:

- EN 61000-6-3:2008+A1:2012
- EN 61000-4-3:2007 +A1:2008+A2:2011

Informacje dodatkowe:

Additional information:

- Conformity evaluation were carried out by Laboratorium Badawcze Oddziału Instytutu Elektrotechniki in Gdańsk, accredited by PCA (AB007),examination report nr 037/LMC-934/2014 from 20.05.2014 r.

Per pro Director of AXIS Sp. z o.o.:

Production Manager Jan Kończak

Gdańsk, 22-10-2015 r.

Notes